Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S9	6	calipers WITH interpolat\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 21:08
S15	7	multiple WITH calipers WITH measurements	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 21:12
S18	134	calipers WITH combination	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 21:13
S19	10	calipers WITH set near3 measurements	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 21:14
S21	16	calipers SAME set near3 measurements	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 21:15
S22		calipers SAME set near3 measurements NOT S19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 21:16
S25	21	(multiple or several) adj calipers NOT S19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 22:05
S27	12	reference adj line WITH tolerance near3 range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 00:06

		,	,			
S28	2	image same reference adj line WITH tolerance near3 range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 00:07
S29	12	reference adj line WITH tolerance near3 range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 00:11
S30	45	image WITH reference WITH tolerance near3 range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	·OR	OFF	2007/11/13 00:12
S33	81	white adj light AND (382/141). ccls. AND inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 01:00
S34	3	white adj light AND (382/141). ccls. AND gray-scale	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 01:02
S37	11	white adj light WITH resolution SAME inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 01:04
S39	68	white adj light WITH resolution AND inspection AND manufactur\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 01:07
S46	32	white adj light WITH inspect\$3 AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 01:14

	,				,	
S47	43	white adj light SAME inspect\$3 AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/13 01:15
S48	22	white adj light SAME inspect\$3 SAME defect AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 01:16
S49	. 55	white adj light AND inspect\$3 SAME defect AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 01:45
S50	. 2	(382/141).ccls. AND (internet or intranet) WITH connection WITH analysis	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 01:47
S51	5	(382/141).ccls. AND (internet or intranet) WITH connection WITH image	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 01:53
S58	27	processing adj unit near2 within near2 sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:07
S61	27	processing adj unit near2 within near2 sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:09
S62	10	processing adj unit near2 within near2 camera	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:10

	1		η	Γ		1
S63	36	processing adj unit near2 in near2 (camera or sensor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:10
S64	3	processing adj unit near2 in near2 (camera or sensor) AND inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:11
S65	12	processing adj unit near2 in near2 (camera or sensor) AND manufact\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:12
S68	3	(computer or processing) near3 (within or inside or in) adj (camera or sensor) AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:17
S69 _.	67	(computer or processing) near3 (within or inside or in) adj (camera or sensor) AND "382".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:18
S70	9	(computer or processing) near3 (within or inside or in) adj (camera or sensor) AND inspection SAME manufactur\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:19
S72	39	(computer or processing) near3 (within or inside or in) adj (camera or sensor) AND inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:35
S73	20	(computer or processing) near3 (within or inside or in) adj camera AND inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:36

11/13/2007 7:15:51 AM C:\Documents and Settings\erice\My Documents\EAST\Workspaces\10533804b.wsp

Page 4

S74	51	(computer or process\$3) near3 (within or inside or in) adj camera AND inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/11/13 02:36
S75	7	(computer or process\$3) near3 (within or inside or in) adj camera AND inspection WITH manufact\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:38
S76	11	(computer or process\$3) near3 (within or inside or in) adj camera AND inspection SAME manufact\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:38
S77	35	(computer or process\$3) near3 (within or inside or in) adj camera AND inspection AND manufact\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:39
S78	28	(computer or process\$3) near3 (within or inside or in) adj camera AND inspection AND manufact\$5 NOT S75	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/11/13 02:38
S79	37	(computer or process\$3) near3 (within or inside) adj camera AND inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:39
S81	79	(computer or process\$3) near3 (within or inside) adj camera AND "382".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 02:40
S82	5	(computer or process\$3) near3 (within or inside) adj camera AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	ON	2007/11/13 03:05

		г		· · · · · · · · · · · · · · · · · · ·		T
S84		(3-D or 3D or three-dimension\$3 or three adj dimension\$4) adj display AND (382/141).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 03:27
S85	44 9	(3-D or 3D or three-dimension\$3 or three adj dimension\$4) adj display AND "382".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 03:27
S87	69	(3-D or 3D or three-dimension\$3 or three adj dimension\$4) adj display AND "382".clas. AND manufacturing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 03:28
S88	7	(3-D or 3D or three-dimension\$3 or three adj dimension\$4) adj display AND "382".clas. AND manufacturing SAME inspection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 03:54
S89	9	reference adj line WITH tolerance adj range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 03:56
S90	14	reference adj line WITH tolerance near3 range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 03:59
S91	5	reference adj line WITH tolerance near3 range NOT S89	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 04:00
S99	100	reference WITH (tolerance near3 area) NOT S89	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 04:04

11/13/2007 7:15:51 AM C:\Documents and Settings\erice\My Documents\EAST\Workspaces\10533804b.wsp Page 6

S10 0	3	inspection adj area AND reference WITH (tolerance near3 area) NOT S89	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 04:05
S10 1	137	reference adj line WITH (tolerance) NOT S89	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 04:06
S10 2	6	reference adj line WITH (tolerance) near2 (area or region or range) NOT S89	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 04:07
S10 3	5	reference adj line WITH (tolerance) WITH bound\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/13 05:30

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S11	97	(adjacent or neighbor\$5) adj calipers	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:15
S13	5	(adjacent or neighbor\$5) adj calipers AND orthogonal	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 00:50
S14	97	(adjacent or neighbor\$5) adj calipers	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:19
S15	3	(adjacent or neighbor\$5) adj calipers AND (adhesive or glue)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:19
S16	48	(adjacent or neighbor\$5) adj calipers AND manufactur\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:22
S17	11	(adjacent or neighbor\$5) adj calipers AND (collinear\$3 or co-linear\$3 or colinear\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:23
S18	22	calipers SAME (collinear\$3 or co-linear\$3 or colinear\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:23
S19	13	calipers SAME hypothesis	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:24

S20	13	calipers SAME (hypothesis or hypotheses)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:29
S27	7	point-to-point WITH caliper	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/11 23:32
S32	5	edge-to-edge WITH caliper	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 00:52
S33	. 79	edge WITH point WITH caliper	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2007/11/12 00:52
S34		edge WITH reference adj point WITH caliper	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/12 00:54
S40	97	adjacent adj calipers	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 01:03
S70	6	382/141 AND quality WITH external WITH control	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:26
S77	126	quality WITH external WITH command NOT S70	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	ON .	2007/11/12 02:31

S78	21	quality WITH external WITH command WITH unit NOT S70	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:33
S81	224	(382/141).ccls. AND (quality or parameter or criteria) AND external\$3 NOT S70	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWEŅT; IBM_TDB	OR .	ON	2007/11/12 02:35
S82	68	(382/141).ccls. AND (quality or parameter or criteria) AND external\$3 WITH (command or control\$3) NOT S70	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:36
S83	22	(382/141).ccls. AND (quality or parameter or criteria) AND external\$3 near2 (command or control\$3) NOT S70	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:36
S85	i8	(382/141).ccls. AND (quality or parameter or criteria) WITH external\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:37
S86	15	(382/141).ccls. AND (quality or parameter or criteria) WITH external\$3 NOT S70	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:40
S88	2	quality adj parameters WITH external WITH control	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:42
S90	29	quality adj parameters WITH external\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:47

S91	831	quality WITH (sets or setting or set) WITH external\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:47
S92	119	quality WITH (sets or setting or set) WITH external\$3 WITH control	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:47
S93	24	quality WITH (sets or setting or set) WITH external\$3 WITH control WITH unit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	ON	2007/11/12 02:51
S94	120	quality WITH external adj device WITH (control\$3 or sett\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:52
S96	· 15	quality near2 (parameters or criteria or standards) WITH external adj device	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/12 02:57